DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003573 Address: 333 Burma Road **Date Inspected:** 18-Aug-2008

City: Oakland, CA 94607

OSM Arrival Time: 1400 **Project Name:** SAS Superstructure **OSM Departure Time:** 2230 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Xia Yong Zheng N/A **Inspected CWI report:** Yes **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower

Summary of Items Observed:

CALTRANS Quality Assurance (QA) Inspector, Alfredo Acuna was present for the fabrication scheduled for this project at the ZPMC facility in Shanghai, China for the San Francisco Oakland Bay Self Anchored Suspension Bridge.

The QA inspector observed ZPMC performing layout, cutting, beveling, milling, fitting and welding activities in bay # 1 and 2 on Tower Assembly shop.

The QA inspector observed ZPMC welding operator Xu Yue Shui # 040781 performing welding operations with the submerged arc welding (SAW) process using the WPS-BT2221-U3 c-S in the flat (1G) position at the junction of the weld joint # WSD1-SA10 A/K-16B. The QA inspector performed welding parameters verifications. The QA inspector found that the welding parameters appeared to be in compliance with the contract documents.

The QA inspector observed ZPMC welding operator Cao Guimei(047304) performing welding operations with the submerged arc welding (SAW) process using the WPS-BT2221-U3 c-S in the flat (1G) position at the junction of the weld joint # ESD1-SA77 A/E-50B skin plate connection. The QA inspector performed welding parameters verifications. The QA inspector found that the welding parameters appeared to be in compliance with the contract documents.

The QA inspector observed ZPMC performing heat straightening operations at the skin plate WSD1-SA 39 A/K for the skin E, West Shaft beside the weld joint 15A and 15B correcting a 3 mm total deformation according with HSR1(T)-3291. ZPMC's heat straightening operations appeared to be in compliance with the contract documents.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

The QA inspector observed a flame notche up to 15 mm of depth at the stiffener from the skin B East shaft, plate # 379 B (middle stiffener). The QA inspector had a conversation with the ZPMC CWI Xia Yong Zheng. The QA inspector asked Mr. Xia the procedure follow by ZPMC for flame notches repair. Mr. Xia reply that ZPMC was welding them without requesting for approval of the Enginner. The QA inspector had a conversation with Task leaders Albert Carreon, Joe Lanz. The QA inspector brought to their attention that ZPMC was performing flame notches repair without approval of the Engineer. Later, the QA inspector had a conversation with ZPMC QC representative Xu Jun. The QA inspector asked why ZPMC was not requesting the Engineer for approval before repairing the flame notches. ZPMC representative showed the QA inspector a letter from ABF representatives directing ZPMC welding flame notches according with the approved base metal repair procedure ZPMC's WQCP. The QA inspector said that most of the steel was designed on the contract drawing on tension and reversal of the stress members and according with the AWS D1.5 flame notches needed to be tested by magnetic particle and ultrasonic and ZPMC's WQCP was not covering this condition. The QA inspector informed to caltrans task Leaders about the conversation held with Mr. Xu and gave the letter from ABF directing ZPMC to repair flame notches without requesting for Engineer approval.

Summary of Conversations:

As noted above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco, 858 344-8746, who represents the Office of Structural Materials for your project.

Inspected By:	Acuna, Alfredo	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer